

2021 to 2024

**Q80052208 - Hyper terminal connects to
ARC-8050T3U, using port 992, get halted all the
time, how to make connection?**

The default telnet port is 993 for TLS connection. Since hyper terminal does not support TLS, please change the controller telnet port setting to 23 for hyper terminal management.

Unique solution ID: #1999

Author: Simone

Last update: 2022-08-11 05:28