2021 to 2024

Q80012212 - Running Monterey 12.6 on an M1 Studio Ultra, ARC-8050T3-24R gets stuck in an infinite boot loop. If I remove the thunderbolt cable from the M1 Studio, allow the computer to fully boot up and log in, then plug the cable in I have no issue mounting it.

The M1 Mac does not wait enough time for the ARC-8050T3-24R to prepare the connected drives. This can be solved to login raid controller web manager console and disable the raid controller BIOS. The BIOS setting in advanced feature menu default setting is auto, please disable it. Apple seems extend the waiting time after latest macOS13 update. You do not need to disable bios after OS updated.

Unique solution ID: #2029

Author: Simone

Last update: 2024-07-21 15:25