

**2021 to 2024**

**Q80022212 - Running Ventura on M1 Studio, the computer is restarting every time it wakes up from sleep attached with ARC-8050T3U-4/4A.**

It only happens on Marvell ROC inside the ARC-8050T3U-4/4A. Update the firmware to V1.65 or later version for this workaround.

Unique solution ID: #2030

Author: Simone

Last update: 2024-07-21 15:25