

2021 to 2024

Q10011905 - The 1.56 firmware makes my DELL r720 unbootable - it stuck on "initializing firmware interfaces". I have switched back and boots again.

We had modified the bios code to fix compatible issue with some supermicro boards. This modification may be not compatible with DELL r720. To avoid similar problem, you can update firmware without updating the bios code in future. The bios code works independent of the firmware code.

Unique solution ID: #1787

Author: Simone

Last update: 2020-08-25 10:48