

2021 to 2024

Q80012111 - Can not upgrade the latest driver/utility in install-mraid-20201224-BigSur.dmg Mac Pro 6,1 (2013)running Mac OS Catalina 10.15.7.

Please follow below steps to check any issue:

- (1). In Mac system information page, please check the **Hardware > PCI** page to see if the box is listed with driver loaded state.
- (2). If raid box is detected but driver not loaded, please check the **Software > Extensions** page to make sure the ArcMSR.kext is listed inside.
- (3). If box is detected and driver is installed but not loaded, please check your system security policy to make sure your system allows this driver been loaded. For system security setting, disable SIP, restart, install the Driver/Utility, and restart and then re-enable SIP.

Unique solution ID: #1976

Author: Simone

Last update: 2021-11-23 09:27