

2021 to 2024

Q60011912 - When commissioning s an ARC-8070 new volume under Linux, a number of index tables (I-node tables) are distributed over the entire volume.

The root cause is the behavior of the Linux OS. You can use the firmware version 1.69-20191028 to avoid an OS related issue.

Unique solution ID: #1850

Author: Simone

Last update: 2020-08-26 05:08