

Q10031410 - Two Bad drives: Hus724040ale640 connected to Areca 1882X, can't power on server and time out after 300secs.

This issue has be fixed into firmware 1.52 date: 2014-09-11 or later.

Unique solution ID: #1213

Author: Simone

Last update: 2022-01-06 07:02