

Q40011508 - USB 3.0 Port of the 5040 sometimes detects only with 2.2TB Size (original size 18TB) in combination with Macbooks or Notebooks which are built 2014 or newer.

This greater than 2TB flag detective issue has been fixed in firmware and bootcode version 1.50 date: 2015-08-12 or later.

Unique solution ID: #1489

Author: Simone

Last update: 2022-01-06 07:06