

2012 to 2013

**Q10061310 - I have three Samsung 840 EVO SSDs
on ARC-1264il-12 and every time I install
windows, the array I'm installing to break.**

It is a bug of Samsung 840 SSD firmware that it can not accept no-zero port number on the multiplier.

Unique solution ID: #1290

Author: Simone

Last update: 2015-08-24 10:40