

2012 to 2013

**Q10031312 - SuperMicro X9DRW-iF can not work
with ARC-1882ix-24 using Riser card RSC-
R2UW-4E8 on the upper slot.**

It is an issue from PCIe bus number. Please update the boot code and firmware to version 1.52 date: 2013-12-11 or later. This firmware disables the PCIe Link Down Reset function.

Unique solution ID: #1304

Author: Simone

Last update: 2015-08-24 11:25