

2012 to 2013

**Q10031204 - Using an Areca ARC-1880i with MSI
interrupt support on recent versions of DragonFly
3.1 causes disk throughput to slow to a crawl
after a while.**

Disabling MSI support by setting `hw.arcmsr.msi.enable=0` in `/boot/loader.conf` is enough to make the problem go away.

Unique solution ID: #1348

Author: Simone

Last update: 2022-01-06 08:29