

2012 to 2013

Q10011211 - The ARC-1882ix-12 never boot with the bad (not spin at all) WD VelociRaptor HD. If insert 3 or more disks (Known good) any warm boot will hang at the 300 screen.

The issue comes from the compatible with 6Gb/s LSI SAS expander. It has fixed by the ARC-1882 firmware version 1.51 date:2012-11-01 or later.

Unique solution ID: #1357

Author: Simone

Last update: 2022-01-06 08:30