

# **Q80011311 - I couldn't get Mac OS X Mavericks boot from the raid volume on both 8050 and 5026, both thunderbolt failed. However, with the same raid volume, it boots no problem with USB 3.0 connection on 5026.**

Please set the BIOS Selection option on the Advanced Configurations to EFI.

Unique solution ID: #1324

Author: Simone

Last update: 2022-01-06 07:11