

2021 to 2024

Q40011912 - When commissioning an ARC-8070 new volume under Linux, a number of index tables (I-node tables) are distributed over the entire volume.

The root cause is the behavior of the Linux OS. You can use the firmware version 1.69-20191028 to avoid an OS related issue.

Unique solution ID: #1827

Author: Simone

Last update: 2020-08-25 11:10