

Q80021312 - I see the limited number USB 3.0 volumes on ARC-5026. If using the Thunderbolt side only you can have 128 volumes. Any one of the Thunderbolt volumes can be marked as SCSI CH:0/LUN:0/ID:0 and only that volume can be shared with USB 3.0 side.

We add an USB3.0 to SATA Bridge to the ROC SATA port for USB3.0 support. SATA target mode port multiplier function is used to emulate multiple logical devices. But SATA target mode port multiplier function is blocked by ROC controller on ARC-5026.

Unique solution ID: #1328

Author: Simone

Last update: 2022-01-06 07:12