

2016 to 2020

Q80031407 - Since updating my 2013 Mac Pro OS to 10.9.4, I get a kernel panic on startup when my 8050 enclosure is attached via Thunderbolt.

The kernel panic issue comes from the iTunes 11.3 update. The solution was to remove the iTunesHelper applications from the user login items. Sometimes iTunesHelper freaks out and causes system hangs. iTunesHelper.app is autoloaded during system boot in Mac OS X, but if you're having problems with the iTunesHelper app you can easily disable this from auto-loading.

Unique solution ID: #1570

Author: Simone

Last update: 2016-02-16 04:53