

**2016 to 2020**

**Q80021607 - ARC-8050T2 has been working perfect up until last week it keeps rebooting itself.**

It may be caused by bad cable or port connection. You validate with another cable and the other port to isolate the reason.

Unique solution ID: #1618

Author: Simone

Last update: 2022-01-06 07:31