

2016 to 2020

**Q80011705 - If I schedule volume check,
ARC-5026 volume check starts every time I power
up unit.**

It is a time info inquiry bug, and causes abnormal volume check time. This issue is fixed and updates firmware version 1.54 date 2017-03-27 or later to workaround it.

Unique solution ID: #1688

Author: Simone

Last update: 2022-01-06 07:27