

2016 to 2020

Q80021901 - ARC-1224/5028T2 cannot recognize more than one D3-S4510 SSD drive. With 12x6 or 1883 controllers the SSDs do not have such behavior.

Please update the firmware to V1.56 2019-1-24 or later version for this workaround.

Unique solution ID: #1863

Author: Simone

Last update: 2020-08-26 06:15