

Q30011202 - ARC-1300-4i and a hp sas expander works perfectly in windows 7. After a fresh install of windows 7 driver version 6.0.0.4, the areca card does not work if the expander is attached.

It is caused by the driver version 6.0.0.4. Update the driver to version 6.0.0.6 for this workaround.

Unique solution ID: #1368

Author: Simone

Last update: 2021-02-04 10:17