

Q40011108 - After changing the "Inband SAS enable" to enabled in the telnet interface of our ARC-8060, the telnet and web interface are not available.

Enable the "inband SAS" feature, it will close the ethernet port to prevent resource confliction. You will be not able to login the controller through ethernet if you enable inband SAS. If you would like to configure the controller, you must use inband SAS or serial port. You have to use the RJ11 to RS232 cable to login the controller serial manager console through the RJ11 connector on the ARC-8060.

Unique solution ID: #1442

Author: Simone

Last update: 2021-02-04 10:20