

Q80041308 - I have an 8050 that can not be detected by P8Z77-V PREMIUM on cold or restart. The 8050 works fine if I plug it in after windows starts up.

This problem has solved just a simple M/B bios update.

Unique solution ID: #1320

Author: Simone

Last update: 2022-01-06 07:11