

Q60011807 - ARC-9200 firmware is not able to register the Hitachi Ultrastar 4U Data102 we have here.

Controller firmware reserved resource is not big enough for the Hitachi Ultrastar Data102 4U 102 bay JBOD. Please update firmware to 1.55-2018-0619 or later for more hardware monitor resources allocation.

Unique solution ID: #1834

Author: Simone

Last update: 2021-02-04 10:57