

Q10052103 - SATA Power Up In Standby does not seem to work with ARC-1883ix-24 and latest firmware.

ARC-1883 RAID adapter ROC PL library does not support PM2 function. SATA Power Up In Standby does not work on ARC-1883 series RAID adapters.

Unique solution ID: #1960

Author: Simone

Last update: 2021-03-25 11:07