

2016 to 2020

**Q60011912 - When commissioning s an ARC-8070
new volume under Linux, a number of index
tables (I-node tables) are distributed over the
entire volume.**

The root cause is the behavior of the Linux OS. You can use the firmware version 1.69-20191028 to avoid an OS related issue.

Unique solution ID: #1850

Author: Simone

Last update: 2020-08-26 05:08