

**2010 to 2015**

**Q30011202 - ARC-1300-4i and a hp sas expander works perfectly in windows 7. After a fresh install of windows 7 driver version 6.0.0.4, the areca card does not work if the expander is attached.**

It is caused by the driver version 6.0.0.4. Update the driver to version 6.0.0.6 for this workaround.

Unique solution ID: #1368

Author: Simone

Last update: 2021-02-04 10:17