

2010 to 2015

**Q30011507 - ARC-1320-8i can only recognize one
when two LTO tape drives connect on each port.**

Please update the driver to date: ArcSAS-2.0.4-10.9-20150618 to fix this issue.

Unique solution ID: #1390

Author: Simone

Last update: 2015-08-24 09:51