

Q10011805 - When powering on and the ARC-1203-2I RAID-BIOS starts, the firmware accepts absolutely no input from keyboard using Asus Mainboard P10S-V/4L BIOS3103.

You can make an USB-Boot stick with the good old MS-DOS, downloaded the latest BIOS from Asus and flashed the Mainboard to fix this issue.

Unique solution ID: #1744

Author: Simone

Last update: 2022-01-06 07:40