

2010 to 2015

Q50011311 - ARC-4036ML Fan keeps on/off repeatedly when it firstly powers on 5 minutes and then it switches on host system later.

This is the EPLD detective issue only happened on Seagate HDD. It can be fixed by updating the EPLD code on the ARC-4036ML.

Unique solution ID: #1311

Author: Simone

Last update: 2021-02-04 10:37