

2010 to 2015

Q50011005 - We don't know what is going on with 4-bay PSUs but today another customer complain 4-bay PSU (arc4020) died.

The amount of load required by a particular power supply is often specified as its minimum load. The ARC-4020 series need to install one HDD for the minimum load. Otherwise, it can not power on.

Unique solution ID: #1482

Author: Simone

Last update: 2021-02-04 10:36