

2011 to 2015

Q80011312 - ARC-5026 works fine with thunderbolt, but when connected via USB 3.0, none of the partitions I've made shows.

Thunderbolt host can support up to 128 volumes and USB 3.0 host only one. Only the SCSI Ch/Id/Lun=0/0/0 volume bonds both Thunderbolt and USB 3.0 connection. You can swap other volumes SCSI Channel/SCSI ID/SCSI Lun with SCSI Ch/Id/

Lun=0/0/0 if you need to access it from USB 3.0 port.

Unique solution ID: #1327

Author: Simone

Last update: 2022-01-06 07:12