

2009 to 2011

Q10011101 - The ARC-1880ix-24 doesn't work on an Intel S3000AHV PCIe 1.0a x8 bus. The controller showed its BIOS during boot, windows couldn't find it. It was also weird that pressing TAB/F6 during the raid BIOS had no effect.

This is the master boot code compatibility issue. Update to 1.49 version to fix it.

Unique solution ID: #1375

Author: Simone

Last update: 2015-08-25 04:00