

2009 to 2011

**Q10061112 - With ARC-1880LP (1.49 2011-10-28),
the RAID1 init for two Intel SSD 510 120GB,
SSDSC2MH120A2K5 SSDs take 3:25h.**

There is a bug on the write same command on Intel SSD 510 SSD. It will cause the init process stuck from time to time for approx 10-15 seconds. Please use the firmware from date: 2011-12-15 and later to bypass this bug.

Unique solution ID: #1439

Author: Simone

Last update: 2015-08-25 04:16