

2009 to 2011

**Q10011001 - On one of our RAID servers with
Areca 1680ix-24, we received following errors:
2009-7-31 15:38:48 H/W Monitor Fan Recovered
2009-7-31 15:38:18 H/W Monitor Fan Failed**

Please update the firmware to version 1.47 to solve the power glitter issue.

Unique solution ID: #1447

Author: Simone

Last update: 2022-01-06 07:59