

**2011 to 2015**

**Q40011204 -The LED lights on st3000DM001 HDD's with firmware CC46 continues to flash even no activity. We tried with other disks and they work normal.**

Problem comes from the activity signal from ST3000DM001 HDD using the same method of SAS HDD. If you use Areca side band or ARC-8666 controller's backplane, the activity signal comes from our controller EPLD without any problem. You can try to get the new firmware from Seagate to fix it.

Unique solution ID: #1369

Author: Simone

Last update: 2021-02-04 10:20