

**2011 to 2015**

**Q40011508 - USB 3.0 Port of the 5040 sometimes detects only with 2.2TB Size (original size 18TB) in combination with Macbooks or Notebooks which are built 2014 or newer.**

This greater than 2TB flag detective issue has been fixed in firmware and bootcode version 1.50 date: 2015-08-12 or later.

Unique solution ID: #1488

Author: Simone

Last update: 2021-02-04 10:29