

2018

Q10031503 - What is the max CPU Temperature of an ARC-1212 or at which temperature it starts to log and throttle?

Controller will alarm for over temperature when processor temperature is over 90 degree.

Unique solution ID: #1030

Author: Simone

Last update: 2015-08-24 08:46