

2017

Q10041410 - ARC-1882ix-12 can not recognize in Windows 2008R2 device manager when put into Asus m/b P8P67 WS revolution. Other m/b works fine.

This is a compatible issue with LSI ROC and Asus P8P67 WS. Controllers can work on PCIX16-1/2 slot, but PCIX16-3/4 slot only does not recognize on cold boot, works perfect warm boot.

Unique solution ID: #1148

Author: Simone

Last update: 2015-08-24 09:36