

**2013**

**Q10041301 - I have gotten the following event message on the ARC-1680ix controller.**

**> 2012-04-20 03:11:20 Enc#2 SLOT 06 Device Removed**

**> 2012-04-20 03:11:19 Enc#2 SLOT 06 Device Inserted**

**> 2012-04-20 03:11:12 Enc#2 SLOT 06 Time Out Error**

The Time Out Error HDD will cause the SAS PHY loss and link again if our firmware sends the reset command to the HDD. It has fixed by ARC-1680ix firmware version 1.51 date: 2012-6-14 or later.

Unique solution ID: #1242

Author: Simone

Last update: 2015-08-24 09:46