

2015

**Q10021402 - I am booting Mountain Lion 10.8.5
from a RAID 0 volume on Areca RAID adapter. I
can not boot from that volume after update
firmware package from 1.51 to 1.52.**

It has fixed on firmware version 1.52 date: 2014-02-07 or later.

Unique solution ID: #1073

Author: Simone

Last update: 2015-08-24 09:15