

**2011**

**Q10061106 - We have a problem during the installation of the drivers for the ARC-1210 on an ESXi 4.1.0 server. Following your instructions included in the read-me file of the driver package we use the Vmware vSphere CLI. The command "perl -vhostupdate ..." returns the following error message:**

**"This operation is NOT supported on 4.1.0 platform."**

This problem was caused by the CLI not the latest version. After upgrading to the newest version the driver was successfully installed.

Unique solution ID: #1404

Author: Simone

Last update: 2015-08-25 04:08