

**2015**

**Q30011503 - Ubuntu kernel version 3.5.17 gets kernel panic after ARC-1320 HBA driver is loaded with a Quantum Ultrium 6 drive (Model: AQ285A#900) using LTFS.**

These known LTFS issues were fixed by the driver version 1.1.6.141103.

Unique solution ID: #1041

Author: Simone

Last update: 2015-08-24 09:48