

2015

Q30011504 - ARC-1320ix-16 shows the following message on the X10DRL-I M/B for about 6 minute
“Warning** : Something Wrong With The Adapter!**

This issue only happens with SSD. It can be solved by ARC-1320 BIOS V1.07e /
Date: 2015-4-08 or later.

DS-S12S-G2240-4 is connected.

Unique solution ID: #1043

Author: Simone

Last update: 2015-08-24 09:48