

2018

Q40011805 - I am getting a random 3.3V over voltage error on ARC-5088 RAID controller.

Please update ARC-5088 firmware to 1.54-20180110 or later for this compatible issue.

Unique solution ID: #1749

Author: Simone

Last update: 2018-05-21 06:26