

2021 to 2023

**Q40012201 - ARC-1330 cannot detect the
ARC-8042-12 volume using two SFF-8644 cables.**

Two 4-lanes SAS ports on the SAS host adapter can be applied to the ARC-8042 RAID subsystem. ARC-8042 RAID subsystem firmware will assign as a wide port configuration to both ports. Choose the SAS Port# option '0' for RAID or JBOD mode. There will be no function on the selection of SAS Port# option '1'.

Unique solution ID: #1978

Author: Simone

Last update: 2022-01-06 06:58