

2021 to 2023

Q50012209 - ARC-8028 has constantly an alarming from "Fan". There are no fans connected though.

Please check the dip switch setting on the 8028, there has a dip switch to configure the fan amounts.

Unique solution ID: #2009

Author: Simone

Last update: 2022-09-17 12:54