


2019

## Q80011801 - I am getting a persistent FAN #2 error on ARC-8050T2 chassis.

You can replace fan by a similar cooling fan. Since controller detects fan speed through power consumption of the fan, so please use a fan with similar (SUNON ME92251V2-0000-C99) specification.

Pendec P/N.:ME92251V2167601	
Fan Model No.	ME92251V2-0000-C99
Fan Dimension	92x92x25mm
Voltage	12 Volts
Bearing Type	Vapo Bearing System
Wire Length	80±10mm
Wire Connection	Pin1:Black Pin2:Red Pin3:Yellow
Connector Type	H-2.54-3P
Speed	2700RPM±10%
Notes:	



# 2019

You can contact with our local distributor for possible replacement part. Some distributors have fan modules for customer replacement.

Distributors can be found in our web site:

<http://www.areca.com.tw/wheretobuy/main.htm>

Unique solution ID: #1730

Author: Simone

Last update: 2018-01-05 10:37