

**2014**

**Q80041403 - I used a Mac mini (late 2012, so with "just" thunderbolt 1 technology) with Mac OSX 10.8.5. I just installed only the driver. Everything was fine, but when the Mac goes to sleep (or I call it hibernate) the areca tower is restarting/rebooting every 1 minute until I wake the Mac up.**

This sleep issue has been fixed in driver ArcMSR- V1.3.7-20130815.

Unique solution ID: #1229

Author: Simone

Last update: 2015-08-24 08:28