

2015

Q80011503 - ARC-5026 unit is spontaneously powering off -- and immediately powering on.

The problem turned out to be a defective Corning electro-optical Thunderbolt cable that was causing the ARC-5026 to power-cycle every few seconds.

Unique solution ID: #1066

Author: Simone

Last update: 2015-08-24 06:29