


2019

Q60011811 - ATTO Expresssas H1280 can not work with ARC-8380 SAS RAID subsystem. When we try to write information to the drive it becomes unresponsive. We can web browser ok with no errors and have tried both SAS ports on the SAS card and the Raid unit.

For the ATTO HBA issue, please update the ARC-8380 firmware to version 1.55-20180705 or later. You can also run ATTO Config Tool to change the below setting "Power Centre Pro" to Disabled.



Unique solution ID: #1794
Author: Simone
Last update: 2019-01-03 10:52

Page 1 / 1

(c) 2019 Vincent C. <vincent_chen@abacid.com> | 2019-02-22 20:42

URL: <http://faq.areca.com.tw//index.php?action=artikel&cat=39&id=795&artlang=en>